SIGNAL.XLS

1   [10] Automatic Test Code   E8
     [12] Make sure that light #2 Is   On
     [14] Make sure that light #3 is   OFF
     [17] Test Transmission Time   01
     [19] Enter a time about
           15-20 minutes ahead of
           computer 's time(displayed in
           upper left corner of screen).

2   Hit F4 for Status D.U.C. Menu
     Select "Set Clock"
     Hit "S" and computer will download it's
     time to the panel.

3   Exit Status D.U.C. Menu

4   Hit F3 for D.U.C. Menu
     Select "Download EEprom."

5   After download, exit D.U.C. Menu and go
     to section [17]. Change test transmission time to "99."
     After hitting [Enter], hit up arrow key to highlight
     test transmission time.

6   Hit F3 and select "Download Selected Item."

7   Terminate call.