Communications Receiver/Gateway

D6600

Release Notes

February 2005

1.0 What's New Summary

- New CPU Firmware, Version 01.02.03 (refer to *Section 3.0*)

> ☑ You must upgrade the D6600 to the latest CPU firmware version before you can load multiple line card versions. Refer to Software Upgrade Procedure in the D6600 Operation and Installation Guide (P/N: 4998122704). You must also upgrade to the latest version of the D6200 Software.

- New line card firmware versions:
    - D6640 Line Card Firmware, Version 01.02.02 (refer to *Section 4.0*)
    - D6640 Line Card Firmware, Version 02.02.02 (refer to *Section 5.0*)
    - D6641 Line Card Firmware, Version 20.00.03 (refer to *Section 6.0*)
    - D6690 DataCom Line Card Firmware, Version 30.00.01 (refer to *Section 7.0*)
- D6200 Administration/Programming Software, Version 1.22 (refer to *Section 8.0*)
- Updated literature (refer to *Section 2.0*)
- D6600 Data Sheet

2.0 Updated Literature

The literature is included on the D6600 CD, Version 1.22 (P/N: 4998122699).

Document	Part Number
D6200 Software Operation and Installation Guide	4998154991
D6600 Program Entry Guide	4998122702
D6600 Operation and Installation Guide	4998122704
D6600 Computer Interface Manual	4998122703
D6600 Quick Start	4998122701
D6202 Operation and Installation Guide	4998122713
D6690 SafeCom System Guide	48536
D6600 Card Installation Guide	4998141059

3.0 D6610 CPU Firmware

The D6610 CPU Firmware, Version 01.02.03 contains these improvements:

- Added support for the D6690 DataCom Card
- Support for RB2000
- Support for UK Caller ID
- Caller ID and DNIS/ANI timing modifications
- SESCOA enhancements
- New option 2.2.38 for Modem IIIa^2 account number

4.0 D6640 Line Card Firmware (Version 01.02.02)

The D6640 Line Card Firmware, Version 01.02.02 contains these improvements:

- Two-way audio enhancements
- Caller ID and timing modifications
- SESCOA enhancements
- DNIS/ANI timing features

5.0 D6640 Line Card Firmware (Version 02.02.02)

The D6640 Line Card Firmware, Version 02.02.02 contains these improvements:

- Two-way audio enhancements
- Caller ID and timing modifications
- SESCOA enhancements
- DNIS/ANI timing features

Security Systems

BOSCH

6.0 D6641 Line Card Firmware

The D6641 Line Card Firmware, Version 20.00.03 supports the same features and functions as the D6640.

- Two-way audio enhancements
- Caller ID and timing modifications
- SESCOA enhancements
- DNIS/ANI timing features
- RB2000 support
- Dual tone/1000 Hz
- UK caller ID
- ITI modifications

7.0 D6690 DataCom Line Card Firmware

The D6690 DataCom Line Card Firmware, Version 30.00.01 contains these features:

- Added SafeCom support to the D6600
- D6600 SafeCom automation (refer to *Appendix I* of the *D6600 Computer Interface Manual* (P/N: 4998122703)

8.0 D6200 Adminstration/ Programming Software

After you upgrade the software, the default user and password are available, regardless of the default settings from the previous release.

The D6200 Software does not support Microsoft Windows 95.

The D6200 Software, Version 1.22 contains these improvements:

- Backup dual receiver function
- Added D6690 SafeCom support to the D6600
- RB2000 support
- Supports updated CPU/DSP programming parameters

Recyclable

© 2005 Bosch Security Systems, Inc.
130 Perinton Parkway, Fairport, NY 14450-9199 USA
Customer Service: (800) 289-0096; Technical Support: (888) 886-6189

4998122709E
Release Notes

2/05
D6600
Page 2 of 2