



Technical Bulletins

Technical Update #048

Date : July 23, 1999

Re : Automatic Contact ID

The PC580 v2.3, PC1555 v2.3 and the PC5015 v2.2 support automatic Contact ID, similar to the automatic SIA format.

It should be noted that when automatic Contact ID is used, all zones, whether defined as burglary or fire, will report an alarm code of [130] for burglary alarm, followed by the zone number.

If fire zones are being used, do not use automatic Contact ID. Manually program the correct reporting codes instead.

If you have any questions concerning this matter, please call DSC Technical Support at 800 387 3630, or 877 285 6655 for service in French. We can also be reached by email at dsctech@dscltd.com.

Sincerely,

Harry Scholz
Manager, Technical Sales

Please e-mail comments or questions to: dsctech@dscltd.com

| [Home](#) | [Installation Manuals](#) | [Technical Support](#) |
| [Technical Bulletins](#) | [DLS Software](#) | [App. Notes](#) | [Suggestions](#) |