
Technogram

10/8/99

Affects: Newer POPIT Label sheets that come with each D8125 Popex Zone Expansion Module

Six of the individual POPIT Labels on the sheets (part number 79-07675-000-A) for the 9000 Series Bank One (9-128) and Bank Two (129-248) have a mistake that affects Points

- 012
- 018
- 114
- 132
- 138
- 234

These six labels have switch 6 set to *on*, the correct position for this switch is *off*. Please mark out the number six on the corresponding label to ensure accurate switch setting during installation.

These incorrect labels can be identified by the green tinted paper backing and the date 9/96. Older versions are printed on regular label stock.

Newer corrected labels have the date 10/99 and part number 79-07675-000-B.

Please contact the Technical Support Department (888) 723-9376 should you require Label replacements.



Radionics®

© 1999 Radionics, a division of Detection Systems, Inc.
® The Radionics logo is a registered trademark of Radionics,
PO Box 80012, Salinas, CA 93912-0012, USA
Customer Service: (800) 538-5807

42650B
Technogram

10/8/99
D8125