

Fire•Lite
MS-2410BC Relay Ratings
Technical Supplement

Document 51024 Rev A 8/17/98 ECN 98-380

WARNING:

Form-C Relay Ratings - An incorrect AC rating for the MS-2410BC Fire Alarm Control Panel relays appears on two pages of the Technical Manual Document #50801 Rev. A.

The correct rating for the three Form-C relays, as stated on page 9 of the Technical Manual, is as follows:

2.0 amps @ 30 VDC (resistive), 2.0 amps @ 30 VAC (resistive)

It is important that the correct rating, as stated above, be inserted on the following pages:

Page 11, Section 1.4 Circuits: In the subsection with the heading **Relays**, change "5.0 amps @ 125 VAC (resistive)" to "2.0 amps @ 30 VAC (resistive)."

Page 23: In the subsection with the heading **Standard Relays**, change "5.0 amps @ 125 VAC (resistive)" to "2.0 amps @ 30 VAC (resistive)."