

DSC 1555&1616 looks like it goes into programming

Step-by-Step 50845466

If when customer arms panel, panel looks like it goes in programming. Make sure quick arm is enabled in panel programming. Section 015, lights 3 and 4 need to be ON.